

**electricity
north west**

Bringing energy to your door



Policy Newsletter October 2024

Rosemary Roberts

Stay connected...



www.enwl.co.uk

Policy Updates – Major Policy Updates



| Ref | Issue | Title |
|--------------|--------|--------------------------|
| CP411 Pt1 N | Iss_21 | LV Cable Jointing Manual |
| CP411 Pt 2 N | Iss_4 | HV Jointing Manual |

Policy Updates – Minor Policy Updates



| Ref | Issue | Title |
|-------|-----------|--|
| ES352 | Iss_12 | Design of Distribution Substations and Transforming Points |
| CP608 | Section 9 | Paralleling Matrices |

Major Policy Updates





Section 2 – Standard Techniques

Update of Standard Technique 1 – Preparation for Jointing.

- The section covering excavations of joint bays has been updated to remove the statement that any excavated spoil should be placed 1 metre away from the joint bay sides. As this was deemed unpracticable in most circumstances, the text has been updated to state excavated spoil shall be positioned a distance equal to the joint bay depth away from the edge wherever practical.
- A statement has been added to state it is the jointers responsibility to ensure the joint bay is safe and a POWRA has been carried out to check and mitigate any risks from collapse or movement of spoil.

Note: This mirrors information updated in the 11kV jointing manual ST1.





Section 2 – Standard Techniques

Update of Standard Technique 1 – Preparation for Jointing.

- The section covering excavations of joint bays has been updated to remove the statement that any excavated spoil should be placed 1 metre away from the joint bay sides. As this was deemed unpracticable in most circumstances, the text has been updated to state excavated spoil shall be positioned a distance equal to the joint bay depth away from the edge wherever practical.
- A statement has been added to state it is the jointers responsibility to ensure the joint bay is safe and a POWRA has been carried out to check and mitigate any risks from collapse or movement of spoil.

Note: This mirrors information updated in the 11kV jointing manual ST1.




Minor Policy Updates





- Update of Appendix D with additional and revised versions of standard drawings.





- Routine update to paralleling matrices.



Archived Policies





CP025 – Preparation and Maintenance of the Long-Term Development Statement

This document has been withdrawn to allow for an update.

Once all the new processes associated with implementing the new Ofgem rules are clear and used for at least one LTDS update, CP025 will be revised and reintroduced.

